



RS246.com Forum :: The World's #1 Audi R, S and RS Enthusiast Website

Advanced search

< [HomePage](#) > < [Classifieds](#) > < [Gallery](#) > < [Privacy Policy](#) > < [Site Rules](#) > < [Sponsorship](#) >

[Board index](#) < [Audi RS & R Discussion Forums](#) < [RS6 / RS6 plus \(C5\)](#)

[Like Like](#)

[f](#) You and 1.692 others like this. 1.692 people like this. [Sign Up](#) to see



[User Control Panel](#) (0 new messages) • [View your posts](#) • [View new posts](#) • [View unread posts](#)

[FAQ](#) [Gallery](#) [Members](#) [Logout](#) [[mavada](#)]

Fiat 500

fiat.nl/500

Ontdek de nieuwe Fiat 500. Vraag nu een proefrit aan.



AdChoices

Cambelt change.... its been emotional

POSTREPLY

First unread post • 2 posts • Page 1 of 1



QUOTE

Cambelt change.... its been emotional

by [Nobby](#) » 05 Sep, 2013 - 23:02

So I started on saturday and there were a couple of hiccups along the way, but I got there in the end. Probably spent around 18 hours in the end, excluding time taken to reseal my intercoolers (more on that later) which I don't know how compares to the book time.

Its the first major bit of work I've done on the Audi but I'm not stranger to cambelt changes just not on this car.

Anyway enough of the chit chat. Here's some more detail. I haven't included a step by step guide of how you do it because that it available in ETKA. The interpretation from ETKA is a little hard to decipher sometimes so I spent lots of time double checking things and inevitably found a few things that didn't seem to be mentioned before.

Day 1: Lots of you would have seen this photo before. Bumper, lights, airbox & pipes all removed. Coolant draining from radiator. Lock carrier bolts screwed in (highlighted in red rings).



[Nobby](#)
4th Gear

Posts: 604
Joined: 14 Dec, 2011 - 14:31
Location: Oxon





Not much of space in there. Not exactly loads when its moved out either.



Perfect fit to stop things drop down to the turbos (!). VO5 'Messy Look' Wax tubs. I believe chunky also uses it 🤔
Red ring shows the damage to the MAF seals. Bloody things.



A bit more space now. Air inlet removed. I'd also removed the intercoolers by this point.



And this is what we have to work with. Should be enough unless you have fists like Bluto.




And thats TDC. As per guide the marker on the crank pulley aligns with a plastic bit, but note the cams will either be aligned or 180 degrees out. Large holes on cam keys need to be on the inside otherwise the locking tool doesn't fit anyway. When in this position Cylinder 5 (first in from the right, number is also on the coilpack wire) is at TDC. For re-assurance I also found the exact TDC with a dial gauge and massive protractor method. The audi damn near too. And the locking tool only has a teenie tiny bit of slop.



Crank locker also fits in down on the passenger side of the block. Quite hard to find at first and a few pipes need to be removed to see it. You can feel the crank if you stick your finger through. Screw in lock all the way.



And here is a larger shot so you can see a bit better.



All the moving bits

A - Left camwheel (for cylinders 1-4)

B - Fixed Roller

C - Waterpump

D - Fixed roller

E - Right camwheel (for cylinder 5-8)

F - Adjuster

G - Crank nose bolt/pulley

H - Movable tensioner

I - Aux belt tensioner

J - Alternator pulley

K - Aux belt fixed pulley

L - Cambelt. Thermostat is behind here.

Behind I & K is the tensioner damper for H.



Tensioner damper and movable pulley. B has a piston in the middle which pushes arm up down and tightens or loosens when needed. These are housed behind a few other things, namely the aux belt (or accessory belt as some people call it). There is also a fairly huge bit which wasn't mentioned when I looked in ETKA and it's my new favourite bit of the car. It's the torque damper. It's basically a mount that stops the engine rocking sideways under the immense torques! (muscle car style)




Most of the bits removed. Pretty dirty down there so I gave it all a good clean out. Area circled is where the thermostat is behind.



A view the other way. For some reason when I removed the camwheel the cam actually rotated. The flat section is supposed to be vertical. At this point I nearly died. I reattached the camwheel and turned it back but it keep springing back. Its seems as though its just a natural place for the cams to turn a little. Panic over.



Thermostat housing now removed.



All the new parts* I will try to put up part numbers to help everyone out.

A - Coolant. Ready mixed 1:1. I bought 6 litres of the stuff in total

B - Waterpump and gasket

C - Movable roller

D - Damper for C

E - Thermostat and gasket

F - 2x fixed rollers

G - Tensioner

H - Aux belt fixed roller (* item pictured is actually the wrong one - from an N/A 4.2 v8 and not the RS6). I ordered the correct one and picked it up later.

I - Aux belt (God its long!)

J - Cambelt

K - Cambelt change Sticker


I didn't change the aux belt tensioner as mine has been replaced in the last years anyway.



All fitted and checking the timing. 2 rotations and check that the locking tools still fit in. Bar across top connects both cam wheels.



And check again just to make sure....



And do it again.....



Day 2, 3 and 4 were spent getting the new parts from Audi and sealing my intercoolers. Both coolers were leaking in the end but I think I did a good job with the JB weld. Both seal now and hold 22 psi for 10 minutes each. Lets just see how long they last. When I did the first test drive there is definately more poke, and I'm not getting TC light flashing on in 2nd and 3rd in the dry 🤔

Aux belt back on



It probably would have been cheaper to just buy the proper tool eh.



And thats it. Its always a scarey moment when you turn it over for the first time, expecting a loud bang and hot metal shards being strewn across the driveway.

Now then. One last thing.....where should I put the [Sticker](#) for the cambelt change?


Daytona RS6 Avant

Rule #36 - At least one gear shall be dropped for every tunnel travelled

**** NOW AVAILABLE ** C5 RS6 Cambelt Tool kit rental (also fits other models 3.7/4.2 V8 engines)**

Re: Cambelt change.... its been emotional

 by [chunky79](#) » 06 Sep, 2013 - 05:39

Chris, that is a splendid write up. 
How did you get the ramps under the front wheels? Did you jack it up and slap them under?
Tis very true that I use the "Messy look wax" on my bum hair, I style it the same as your barnet!

previous- 205 gti, 306 gti, S3, S4 V8 avant.
Now- C5 RS6 [Misano red](#) avant. Getting close to how I want it.

If you don't know where you're going, any road will take you there!



 **QUOTE**



chunky79

Cruising

Posts: 6187
Joined: 25 Feb, 2007 - 10:51
Location: West Mids



ONLINE



Display posts from previous: All posts Sort by Post time Ascending 

WHO IS ONLINE

Users browsing this forum: [ahoooga](#), Google [Bot], Google Adsense [Bot], [mavada](#), [seaneb](#) and 12 guests



[Board index](#) [Subscribe topic](#) [Bookmark topic](#)

[The team](#) • [Delete all board cookies](#) • All times are UTC

All logos and trademarks in this site are property of their respective owners.

The comments are property of their posters, all the rest © 2002-2012 by RS246 Limited

[RS246.asia](#) | [RS246.be](#) | [RS246.biz](#) | [RS246.co.nz](#) | [RS246.co.uk](#) | [RS246.com](#) | [RS246.es](#) | [RS246.eu](#) | [RS246.in](#) | [RS246.info](#) | [RS246.me.uk](#) | [RS246.net](#) | [RS246.org](#) | [RS246.org.uk](#) | [RS246.tv](#)